

A DORMAN EXCLUSIVE CATEGORY

DORMAN®

OE SOLUTIONS™



FLUID RESERVOIRS COVERAGE GUIDE



NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES

LOOK INSIDE FOR:



COMPLETE RESERVOIR
IDENTIFICATION GUIDE



COMMON FAILURE PATTERN
EXPLANATIONS



TECH TIPS



EXCLUSIVE DORMAN
COVERAGE

COOLANT RESERVOIRS

Pressurized



603-350
VW Beetle 2010-98



LOCATION

- Typically located along fender, in front of strut



COMMON REASON FOR FAILURE

- Crack in reservoir leading to loss of fluid and eventual engine overheating
- Cap failure (not releasing pressure or not properly attached)
- Collision damage



TECH TIPS

- Ensure fluid cools before opening cap
- Ensure level sensor is operating properly (if applicable)

Non-pressurized

(AKA Overflow Bottle)



LOCATION

- Located next to, or attached to radiator; or radiator fan shroud



FAILURES

- Use of fluids other than coolant fluid
- Damaged during replacement of other items (radiator, radiator fan, etc.)
- Collision damage



TECH TIPS

- Ensure radiator is operating properly
- Ensure reservoir is filled only to cold level



603-392
Chrysler Sebring, Dodge Stratus, 2005-01
Mitsubishi Eclipse 2005-98

POWER STEERING RESERVOIRS



603-934
2007-01 Chrysler Caravan, Grand Caravan,
Town & Country, Voyager



LOCATION

- Typically Located behind engine, next to or attached to Power Steering Pump



COMMON REASON FOR FAILURE

- Damaged during power steering pump removal
- Where applicable, o-rings deteriorate creating bad seal
- Where applicable, screen clogs with debris prohibiting free flow of fluid
- Collision damage



TECH TIPS

- Ensure proper seal to power steering pump
- Ensure power steering pump is operating correctly

WINDSHIELD WASHER RESERVOIRS



603-159
Ford Explorer 2010-02, Lincoln Aviator 2005-03,
Mercury Mountaineer 2010-02



LOCATION

- Typically located behind one of the headlights




COMMON REASON FOR FAILURE

- Use of fluids other than wiper fluid
- Road debris puncturing bottle
- Cap may be cracked, missing or improvised as a result of regular DIY fluid maintenance
- Collision damage



TECH TIPS

- Always use Windshield Wiper Fluid. Water expands when frozen and may crack reservoir.
- Some installations may require wheel and wheel well liner removal



FLUID RESERVOIRS

SUPERIOR COVERAGE

WINDSHIELD WASHER RESERVOIRS



73
MILLION

VEHICLES COVERED

POWER STEERING RESERVOIRS



24
MILLION

VEHICLES COVERED

PRESSURIZED COOLANT RESERVOIRS



63
MILLION

VEHICLES COVERED

NON-PRESSURIZED COOLANT RESERVOIRS



52
MILLION

VEHICLES COVERED

224 SKUS COVERING OVER 212 MILLION VEHICLES

NEW PRESSURIZED COOLANT RESERVOIRS

| Make | Model | Year | Dorman # |
|----------|---|---------|----------------|
| Chrysler | Avenger, 200 | 2013 | 603-379 |
| Chrysler | 300, Charger, Magnum | 2010-06 | 603-056 |
| Ford | Fusion, Milan | 2011-10 | 603-333 |
| Ford | Edge, MKX | 2010-08 | 603-353 |
| Ford | F Series Trucks, Expedition | 2010-03 | 603-028 |
| Ford | Mustang | 2010-05 | 603-051 |
| Ford | Grand Marquis, Crown Victoria, Town Car | 2011-98 | 603-050 |
| Ford | Explorer | 2005-02 | 603-070 |
| GM | Cruze | 2013 | 603-383 |
| GM | Intrigue | 2002-00 | 603-143 |
| GM | Malibu, Pontiac G6 | 2006-04 | 603-066 |
| GM | Malibu, Pontiac G6 | 2012-06 | 603-067 |
| GM | Saturn Vue | 2007-02 | 603-238 |
| GM | LaCrosse, Regal, Cadillac SRX | 2012-10 | 603-228 |
| GM | Concours, Deville, Eldorado, Seville | 2002-94 | 603-133 |
| VW | Jett, GTI, EOS, A3, TT, TT Quattro, Passat, R32, Rabbit, Tiguan | 2012-05 | 603-253 |

DORMAN[®]
NEW SINCE 1918

