


New Aftermarket Repair Solution



Covering over
6 Million Vehicles!

90449

Various GM Vortec
6 & 8 Cylinder Engines
2006-92



PROBLEM: Tabs crack and break off distributor base resulting in engine misfire

SOLUTION:



Repair plate designed to repair the broken tabs on the distributor housing and properly align the cap during replacement/installation.



**REDUCE
REPAIR COST**

This repair solution provides up to a 90% savings opportunity by eliminating the need to replace the entire distributor assembly

NEW PRODUCTS • NEW SOLUTIONS • NEW OPPORTUNITIES