

PYROMETER USING STEPPER AND LED LIGHTING HARNESS WIRE IDENTIFICATION AND POSITION



(viewed from the wire IN side of the plug)

WIRING DIAGRAM

- 1. Red to Probe
- 2. Yellow to Probe
- 3. X=Empty
- 4. White Dash Lights, or may be empty for non LED gauges
- 5. X=Empty
- 6. Red-12 volt switched power

EMPTY

- 7. X=Empty
- 8. Black-Gauge ground
- 9. X=Empty
- 10. X=Empty

EMPTY

EMPTY

10

5

