



866-926-2867

Email: info@blackhorseoffroad.com

Mon-Fri 9AM-6PM EST

Headquarters

39 ST. MARY'S PLACE FREEPORT, NY 11520

INSTALLATION INSTRUCTIONS

UASGM05

[Fit 2014-2019 Chevrolet Silverado and GMC Sierra 1500, also 2015-2020 Chevrolet and GMC 2500,3500]

Thank you for purchasing our products! Please contact us for any issues!

Parts List:

- 4 Self Tapping Screws

Tools Needed:

- Impact drill or Socket wrench
- 1/8 Drill Bit
- Phillips Head Drill Bit (optional)

Warning: a) This ahead under-seat storage is fit for the 2014 to 2019 Chevrolet Silverado and GMC Sierra 1500 **with an under-seat console bench seat**. As well as the 2015 to 2020 Chevrolet Silverado and GMC Sierra 2500 and 3500 Series models **with an under-seat console bench seat**. This model fits in the center section compartment under the seat of the split bench models of these vehicles. Note: this model will not fit the 2014 HD trucks (2500 and 3500).

b) To avoid locking yourself out, first set the password with the SAFE DOOR OPEN and test the operation of the lock before closing the safe door.

Safe installation:

STEP 1 Clear out the contents of the console for now, including the factory mat at the bottom of

the console.

STEP 2 Remove the neoprene padding from the inside of the safe.

STEP 3 Place the safe into the console compartment.

STEP 4 Using a **1/8 DRILL BIT** along with a drill, pre-drill pilot holes into the console compartment where the screws will be set.

- a. The screws will be set in the two holes on either side of the safe.
- b. Make sure to drill through until the drill hits the metal.
- c. To make this process easier, mark the locations where the holes will be drilled, remove the safe, then drill the pilot holes into the console compartment.

STEP 5 If you removed the safe from **STEP 5**, reinsert the safe into the console compartment.

STEP 6 Secure the safe into the console compartment using the **4 SELF-TAPING SCREWS**, these screws are to be set into the pre-drilled pilot holes from **STEP 5**.

STEP 7 Tighten the bolts, **DO NOT OVER-TIGHTEN, THIS COULD DAMAGE THE CONSOLE.**