

LED Hidden Strobe Lights USER MANUAL

LIGHTHEAD x 2pcs EXTENSION CABLE FLASHER & CABLE








LIGHT ASSEMBLY INSTALLATION

- 1. Remove the Corner/Head/Tail light from vehicle.
- 2. Select location to mount lighthead.
- 3. Drill 1 inch diameter hole to the light assembly.
- 4. Insert lighthead into hole.
- 5. Apply silicone (user-supplied) for better fit.


WARNING: Do NOT cover heat sink with silicone. It may cause damage to the product and void warranty.



NOTE: Lighthead mounting location may vary depending on the design of the vehicle light assembly.

WIRING TO EXISTING STROBE CABLES

In this configuration, existing strobe extension cables are used to facilitate installation.



NOTE: Wire colors of LED Kit do not need to match wire colors of extension cables.

- RED — To +VDC (fuse @ 5A) BLACK — To Chassis Ground

WHITE · - For Simultaneous or Alternating Flash *refer to "WIRING 2 KITS TOGETHER" on opposite page

- YELLOW – For Synchronization & Flash Patterns Connect YELLOW wires of all Kits together for synchronization *All kits must be set at the same pattern

> Momentarily apply +VDC to YELLOW wire: once for next pattern · guickly three times for reset


FP#	Flash Patterns		
0	Random	10	Double (all)
1	Single (split)	11	Quad (all)
2	Double (split)	12	Quint (all)
3	Quad (split)	13	Mega (all)
4	Quint (split)	14	Ultra (all)
5	Mega (split)	15	Single-Quad (all)
6	Ultra (split)	16	Single H/L (all)
7	Single-Quad (split)	17	Steady 2 (CA)
8	Single H/L (split)	18	Steady 4 (all)
9	Single (all)		

*SPLIT = Head1 alternate Head2 *ALL = Head1 & 2 Simultaneous **NOTE:** This unit may not be factory set at FP# 0.

WARNING: Do not connect LED lighthead directly strobe power supply. It will cause damage and void the warranty.







If "split" flash pattern* is selected: Heads 1&4 will alternate with Heads 2&3.


If "all" flash pattern* is selected: Heads 1&2 will alternate with Heads 3&4.

and select "split" flash patterns.




FLANGE MOUNT INSTALLATION (for kits with Flange option only)

1. Remove Original Base Plate from lighthead base.




2. Secure Flange Plate to lighthead base with screws.



4. Drill marked holes accordingly. 5. Insert lighthead pigtail into wire hole.

3. Use mounting flange to mark wire and screws holes to drill.


6. Place foam, lighthead, and flange in line with the mounting holes, and secure with supplied sheet metal screws.



WARNING: Make sure to use the foams when mounting lightheads.

WIRING 2 KITS TOGETHER

In this configuration, different alternating flash patterns can be achieved.



NOTE: Illustration not to scale.