


Parts List & **Operating Instructions** for:

7704

Four Wheel Drive Ball Joint Service Kit

Application: Used with OTC Ball Joint Press & Service Tools (7248 & 7249) to remove and install the upper and lower ball joints on 1967 - current 4WD vehicles with Dana 44 axles.

Parts List



Item No.	Part No.	No. Req'd	Description
1	38355A	1	Installing Cup
2	38354	1	Receiving Cup
3	204508A	1	Receiving Cup

Safety Precautions



Caution: To prevent personal injury when using these tools,



- Wear eye protection that meets the requirements of ANSI Z87.1 and OSHA.
- Before repairing a vehicle, block the wheels to prevent the vehicle from moving.



 Check the final alignment of tooling and components before using a C-frame press to exert pressure.






Operating Instructions

Removal

- 1.Remove the knuckle assembly from the vehicle according to the instructions in the service manual. *Note:*
- It may be necessary to remove the steering arm before servicing the upper ball joint on the left hand knuckle.
- The lower ball joint must be removed before any service can be performed on the upper ball joint.
- 2.Remove the lower ball joint snap ring.
- 3. Assemble the ball joint press over the ball joint as shown in Figure 1.
- 4.Turn the forcing screw until it meets the ball joint. Check the alignment of all components. Tighten the forcing screw until the ball joint is removed.
- 5. Repeat Steps 3 & 4 to remove the upper ball joint.







Figure 1

Installation

Note: The lower ball joint must be installed before the upper ball joint.

- 1. Clean the knuckle and coat it with a suitable lubricant.
- 2. Assemble the ball joint into the knuckle.
- 3. Assemble the ball joint press components as shown in Figure 2. Check the alignment of all components. Tighten the forcing screw until the ball joint is firmly seated.
- 4. Install the snap ring on the lower ball joint.
- 5. Repeat Steps 1-3 to install the upper ball joint.
- 6. Install the knuckle assembly to the vehicle according to the vehicle service manual procedures.



Installing Cup 38355A
Installing Adapter 204508A

Upper Ball Joint

Figure 2