

Service Bulletin 050016

Issued May 2008 (Revised July 2008)



TF (MB) TG (ME) Torqmotor Seal Kits

SK000092 (Buna Seals), SK000093 (Fluorocarbon Seals)
& SK000099 (Vespel Commutator Seal)

Reference Torqmotor Service Manual SM1512

ITEM	QTY	DESCRIPTION	SK000092	SK000093	SK000099
1	1	BACK UP RING	028515	028515	028515
2	1	BACK UP WASHER	029118	029118	029118
3	5	SHAFT SEAL	032817	032818	032817
4	6	BODY SEAL	032819	032820	032819
5	1	COMMUTATOR SEAL	032435	032435	032439
6	1	DIRT & WATER SEAL	478035	478035	478035
	1	BEARING LUBRICANT	406018	406018	406018
	1	SERVICE BULLETIN	050016	050016	050016

