

#### How to Use:

1. Prep surface to polish using Busch Aluminum Wash. If surface is in good shape, use 50/50 diluted ratio of cleaner. Let surface dry and wipe away any excess water.
2. Surface must be in good shape, free of pitting or imperfections that will inhibit a good shine.
3. Apply Busch Super Shine aluminum polish to terry cloth rag, and wipe onto surface. If using by hand, wipe in back and forth motion until black residue appears. Using separate terry cloth rag, wipe black residue away to reveal the shine. With a machine and buffing pad, lightly wipe the polish onto the surface, coating the entire wheel. Let haze for 5 minutes and buff to a shine.
4. Use Busch Aluminum Wax and Sealant to keep a long lasting shine.

#### Benefits:

- Restores shine to bare, uncoated aluminum with minimal effort. Wipe on-wipe off without all the fuss.
- Can be used by hand or machine. Many competitor polishes only work by hand.
- Polishes all soft metals, such as copper, brass, magnesium, bronze, silver, gold.

Also works well on ferrous metals.

- Contains corrosion inhibitors that shield metal from the elements. Provides a longer lasting shine.
- Black buffing residue is easily washed from hands with soap and water.

When it comes to quality auto detailing & care, Busch is the brand you can depend on.