



CB96559 CONTROL ARM

NEED HELP?

Please call our Technical Support team for assistance from our team of certified automotive experts.

1-866-933-2911



ENGLISH

When removing the OE control arm on specified vehicles, the OE control arm's bushing alignment may differ from this replacement control arm's design. The difference does not affect fitment, and this replacement control arm can be directly installed without modification. Do not attempt to change the replacement arm's bushing alignment.

ESPAÑOL

Al retirar el brazo de control del OE (equipo original) en determinados vehículos, la alineación del buje del brazo de control del OE puede diferir del diseño de este brazo de control de repuesto. La diferencia no afecta el ajuste y este brazo de control de repuesto se puede instalar directamente sin modificaciones. No intente modificar la alineación del buje del brazo de repuesto.

FRANÇAIS

Lors du retrait du bras de commande d'origine sur certains véhicules, l'alignement des bagues du bras de commande d'origine peut ne pas être identique à celui du bras de commande de rechange. Cette différence n'affecte pas le montage et le bras de commande de rechange peut être installé directement sans modification. Ne pas tenter de modifier l'alignement de la bague du bras de rechange.