

INFO

febi
30458

SWAG
20 93 0458

to fit:
BMW
Various Models
4 and 6 Cylinder
engines



EN Attention

When replacing this sprocket, please pay attention to the mounting direction. The collar of the sprocket must face inwards if fitted to the crankshaft, or face outwards if fitted to the oil pump drive.

Every chain tensioner is checked!

The right choice: You have chosen this chain tensioner from the bilstein group engine spare parts range. bilstein group has developed a test bench for chain tensioner in a joint venture with one of the biggest German hydraulic machine manufacturers. The bilstein group test bench accurately simulates the stresses and strains to which the tensioner is subjected in actual service in the engine. All bilstein group hydraulic chain tensioners are 100% inspected using this test bench. Each and every tensioner is individually inspected and tested in all functions, before being passed by the bilstein group quality control department for sale. For you this means even more safety in this very critical area of engine reliability.