

OIL PICK-UP GASKET

431253



Description: OIL PICK-UP GASKET
SKU: 431253
OEM: 1816722C2
Product Group: ENGINE PARTS
Product Class: ENGINE GASKETS, O-RINGS & GASKET SETS
UPC Code: 193807057503
Sell Pack: 5 EA
 (Available to buy in increments of 5)
Weight: 0.05 LBS
Warranty: 2 Years



Details:

Oil Pick-up Gasket
 Year: 1993-2003 International DT408/DT466/DT530E HEUI/DT466E HEUI/530 Engines application

E-Catalog Pages:

| Catalog Page | Description |
|---|---|
| <p>An exploded view diagram of an oil pump assembly. It shows various components including gears, bearings, and housing parts, arranged in a sequence to show their assembly. The diagram is set against a grid background.</p> | <p>International Engine 2019 Oil Pump - DT-466 / DT-530 (1993-1997 PLN)</p> |

Copyright © 2020 PAI Industries, Inc.
 All rights reserved. All content is property of PAI Industries, Inc, and may not be reproduced or redistributed in any form.


Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. PAI is not affiliated with Mack Truck, Inc.®, Volvo®, Fuller®, Cummins®, Eaton®, Rockwell®, Caterpillar®, Freightliner®, Hendrickson®, Kenworth®, Detroit Diesel®, International®, Peterbilt®, or Dana®. All Manufacturer's names, numbers, symbols and descriptions are used for reference only. It is not implied that any part listed is the product of these manufacturers.

OIL PICK-UP GASKET


431253




International Engine 2019
 Rebuild Kit Breakdown - DT-466 / DT-530 (1993-1997 PLN)



International Engine 2019
 Oil Pan - DT-466 / DT-530 (1993-1997 PLN)



International Engine 2019
 Cylinder Block Components - DT-466 / DT-530 (1993-1997 PLN)



International Engine 2019
 Oil Pan - DT-466E / DT-530E (2000-2003)

Copyright © 2020 PAI Industries, Inc.
 All rights reserved. All content is property of PAI Industries, Inc. and may not be reproduced or redistributed in any form.


Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. PAI is not affiliated with Mack Truck, Inc.®, Volvo®, Fuller®, Cummins®, Eaton®, Rockwell®, Caterpillar®, Freightliner®, Hendrickson®, Kenworth®, Detroit Diesel®, International®, Peterbilt®, or Dana®. All Manufacturer's names, numbers, symbols and descriptions are used for reference only. It is not implied that any part listed is the product of these manufacturers.

OIL PICK-UP GASKET


431253

CHART

International Engine 2019
Rebuild Kit Breakdown - DT-466E / DT-530E (2000-2003)




International Engine 2019
Cylinder Block Components - DT-466E / DT-530E (2000-2003)



International Engine 2019
Oil Pump - DT-466E / DT-530E (2000-2003)

CHART

International Engine 2019
Rebuild Kit Breakdown - DT-466E / DT-530E (1993-1999 HEUI)




International Engine 2019
Oil Pump - DT-466E / DT-530E (1993-1999 HEUI)

Copyright © 2020 PAI Industries, Inc.
All rights reserved. All content is property of PAI Industries, Inc. and may not be reproduced or redistributed in any form.


Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. PAI is not affiliated with Mack Truck, Inc.®, Volvo®, Fuller®, Cummins®, Eaton®, Rockwell®, Caterpillar®, Freightliner®, Hendrickson®, Kenworth®, Detroit Diesel®, International®, Peterbilt®, or Dana®. All Manufacturer's names, numbers, symbols and descriptions are used for reference only. It is not implied that any part listed is the product of these manufacturers.

OIL PICK-UP GASKET

431253



International Engine 2019
Cylinder Block Components - DT-466E / DT-530E (1993-1999 HEUI)



International Engine 2019
Oil Pan - DT-466E / DT-530E (1993-1999 HEUI)

Component Of:

| SKU | Image | Description |
|------------------------|-------|------------------------|
| 431263 | | FRONT COVER GASKET KIT |
| 431267 | | FRONT COVER GASKET SET |
| 431277 | | OIL PAN GASKET |

Copyright © 2020 PAI Industries, Inc.
All rights reserved. All content is property of PAI Industries, Inc. and may not be reproduced or redistributed in any form.

Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. PAI is not affiliated with Mack Truck, Inc.®, Volvo®, Fuller®, Cummins®, Eaton®, Rockwell®, Caterpillar®, Freightliner®, Hendrickson®, Kenworth®, Detroit Diesel®, International®, Peterbilt®, or Dana®. All Manufacturer's names, numbers, symbols and descriptions are used for reference only. It is not implied that any part listed is the product of these manufacturers.

OIL PICK-UP GASKET

431253

Cross Reference:

| Manufacturer | OEM Number |
|--------------|----------------|
| MACK | 4333-1816722C2 |
| NAVISTAR | 1816722 |
| NAVISTAR | 1816722C2 |

Copyright © 2020 PAI Industries, Inc.

All rights reserved. All content is property of PAI Industries, Inc, and may not be reproduced or redistributed in any form.

Any reference to OEM names or OEM product identification numbers/descriptions/model numbers is for identification only and does not indicate that it is an OEM part. PAI is not affiliated with Mack Truck, Inc.®, Volvo®, Fuller®, Cummins®, Eaton®, Rockwell®, Caterpillar®, Freightliner®, Hendrickson®, Kenworth®, Detroit Diesel®, International®, Peterbilt®, or Dana®. All Manufacturer's names, numbers, symbols and descriptions are used for reference only. It is not implied that any part listed is the product of these manufacturers.