HELPFUL HINTS:

To eliminate spark and whining noise, unplug the RCA audio cables from one component, for example the amplifier, and temporarily install the ES-034. (See illustration). If the noise is eliminated, then permanently install the ES-034 in that location. If the noise remains, proceed to the next RCA audio connection. If, after all RCA audio signal connections have been tested with the ES-034, and the whining noise still remains, then an additional Scosche Noise Filter may be necessary.

CAUTION: ALWAYS DISCONNECT THE NEGATIVE (-) TERMINAL OF THE VEHICLE BATTERY WHENEVER ATTEMPTING TO MAKE ANY ELECTRICAL CONNECTIONS TO PREVENT SHORT CIRCUITS DURING THE INSTALLATION PROCEDURE. YOU MAY CALL THE SCOSCHE INDUSTRIES TECHNICAL HELP LINE AT 1 (800) 621-3695, EXT. 3.

INSTRUCTIONS

- Unplug the RCA signal cable connectors from the audio component at which the ES-034 will be installed near. Insert the male RCA connectors of the ES-034 into the audio components female RCA receptacles. Then insert the remaining male RCA connectors into the female RCA ends of the ES-034 filter. (See illustration.)
- If previously disconnected, reconnect the negative (-) terminal of the vehicle battery. Start the vehicle and test the sound system for noise.
- Reinstall the stereo into the dash cavity if previously removed.

