



# SPYDER™

## SKU# 5085368



SCAN THE QR CODE TO  
VIEW THE INSTALL VIDEO

### PACKAGE CONTENTS:



• 2X TAIL LIGHT ASSEMBLIES

### FITMENT:

• 2007-2013 TOYOTA TUNDRA

-  [FACEBOOK.COM/SPYDERAUTO](https://www.facebook.com/spyderauto)
-  [LINKEDIN.COM/COMPANY/SPYDER-AUTO](https://www.linkedin.com/company/spyder-auto)
-  [INSTAGRAM.COM/SPYDERAUTO](https://www.instagram.com/spyderauto)
-  [TWITTER.COM/SPYDERAUTO](https://twitter.com/spyderauto)
-  [TIKTOK.COM/@SPYDERAUTO](https://www.tiktok.com/@spyderauto)



SCAN THE QR CODE  
TO VISIT OUR WEBSITE

**WARNING:** BY READING THIS DOCUMENT, YOU AGREE IT IS ONLY TO BE USED AS AN EDUCATIONAL GUIDE. SPYDER AUTO NOR ITS DEALERS MAKE GUARANTEES ON ANY FINISHED RESULTS, NOR ARE THEY TO BE HELD RESPONSIBLE FOR ANY DAMAGE, MISUSE, OR PERSONAL INJURIES. IF YOU ARE UNABLE TO CLEARLY UNDERSTAND AND ADAPT THE INFORMATION BELOW, PROFESSIONAL INSTALLATION IS RECOMMENDED. FOR ANY ISSUES OR QUESTIONS ABOUT YOUR SPYDER PRODUCT, REACH OUT TO OUR TECH SUPPORT TEAM [TECHSUPPORT@SPYDERAUTO.COM](mailto:TECHSUPPORT@SPYDERAUTO.COM). IT IS THE INSTALLER'S RESPONSIBILITY TO CONFIRM COMPLIANCE WITH STATE AND LOCAL LAWS. THIS PRODUCT CAN EXPOSE YOU TO CHEMICALS INCLUDING CHROMIUM (HEXAVALENT COMPOUNDS), WHICH ARE KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER AND BIRTH DEFECTS OR OTHER REPRODUCTIVE HARM. FOR MORE INFORMATION GO TO [WWW.P65WARNING.CA.GOV](http://WWW.P65WARNING.CA.GOV)

**TOOLS REQUIRED:**

- RATCHET
- T30 TORX




**STEP 1:**  
**DISCONNECT THE NEGATIVE BATTERY TERMINAL**



**STEP 2:**  
REMOVE (2) T30 TORX SCREWS



**STEP 3:**  
UNSEAT TAIL LIGHT



**STEP 4:**  
REMOVE (3) BULB SOCKETS



**STEP 5:**  
REMOVE BULB FROM BRAKE SOCKET



**STEP 6:**

**INSTALL BRAKE SOCKET INSERT. (ALIGN BLACK WIRE FROM SOCKET TO BLACK WIRE OF SOCKET INSERT)**



**STEP 7:**

**SEAT (3) BULB SOCKETS ONTO SPYDER TAIL LIGHT**



**STEP 8:**  
**SEAT SPYDER TAIL LIGHT**



**STEP 9:**  
**REINSTALL (2) T30 TORX SCREWS**



**STEP 10:**

**RECONNECT THE BATTERY AND TEST THE FUNCTIONS TO ENSURE THEY FUNCTION PROPERLY**