


PART NO. 532

TOLERANCES UNLESS SPECIFIED		
TWO PLACE DECIMALS +/- .015	THREE PLACE DECIMALS +/- .005	ANGLES +/- 1°



NOTE: Repair Harness Ford Turn Signal Switch.

REPLACES O.E.M. #

				MATERIAL	N/A	SCALE	NTS	WELLS MANUFACTURING CORP. FOND DU LAC, WISCONSIN	
						DATE	2-5-03		DWN. BY GC
				FINISH	N/A	ENGINEER	2-5-03	DAL	
						APPROVED	2-5-03	JSK	
RELEASED DRAWING	25978A	2-5-03	GC			PURCH.	<input type="checkbox"/>	PROD.	<input type="checkbox"/>
L	REVISION	CN	DATE	BY	CAD REF.	N/A	MODEL	TITLE	PIGTAIL
								PART NO.	532

View other wipers and washers made by WVE on our website.