



**PLEASE READ THE FOLLOWING
INSTRUCTIONS BEFORE INSTALLATION.**

Pigtail Replacement

The wire colors of this pigtail may not match the wire colors on your vehicle. If the connector plugs into the component, the pigtail is correct.

Connection

It is strongly suggested to solder the new pigtail wires to the vehicle harness wires utilizing Rosin Core solder and shrink tubing; any other connection is only a temporary repair. Be certain to connect each wire of the new pigtail in the same location as the failed connector.

In some cases, product may not be manufactured by NGK SPARK PLUG CO., LTD (NGK) or its affiliate companies. Any questions regarding this product shall be solely directed to NGK SPARK PLUG CO., LTD or its affiliates at the contact information listed above.

En algunos casos, el producto no puede ser fabricado por NGK SPARK PLUG CO., LTD (NGK)